



ITEM NO.	PART NO.	DESCRIPTION	QTY REQ'D	ITEM NO.	PART NO.	DESCRIPTION	QTY REQ'D
1	27256	Upper Cover (Model AG)	1	17	27072	Armature Assy (with metal cam, incl's item 18)	1
	27259	Upper Cover (Model BG)	1		21977	Armature Assy (with plastic cam, incl's item 18)	1
2	21790	Cord Set (Model AG)	1	18	27251	Metal Cam & Bearing Assembly	1
	21164	Cord Set (Model BG)	1		21976	Plastic Cam & Bearing Assembly	1
3	21692	Screw	2	19	21068	Bearing Mounting Ring	1
4	21366	Speed Control Repair Kit	1	20	21014	Blade Retaining Spring	1
5	21814	Insulation Sheet - Mylar	1	21	S27164	Hinge Assembly (Model AG)	1
6	21758	Insulation Sheet - Copaco	1		S21743	Hinge Assembly (Model BG & Oster 76 & 89 Blade Compatibility)	1
7	21936	Brush Repair Kit	1		S27091	Hinge Assembly (Model BG & Oster 10, 22, 111 Blade Compatibility)	1
8	21766	Brush Housing Assembly (includes items 9, & 10)	1	22	27131	Blade Hinge Screw	2
9	21011	Brush Holder	2	23	64139	Blade Screw	2
10	21021	Set Screw	2	24	64003	Blade Bracket	1
11	27252	Lower Housing (Model AG)	1	25	S64013	Tension Spring	1
	21869	Lower Housing (Model BG -UL/CSA)	1	26	64027	Blade Guide	1
	27253	Lower Housing (Model AG-CSA)	1	27	27181	Front Motor Frame Assembly	1
12	25018	Hanger Bail	1	28	22319	Blade Drive Assembly	1
13	21050	Rear Housing Screw	2	29	15766	Blade Drive Screw	2
14	21048	Front Housing Screw	2	30	21018	Switch Actuating Arm	1
15	21067	Bearing Mounting Ring	1	31	27198		
16	27184	Field Assembly (Model BG)	1				

IMPORTANT INFORMATION

When ordering repair parts, include part number, part name and model of clipper. For best performance, clipper should be CLEANED and OILED with Andis Clipper Oil before and after use. If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin 53177 U.S.A. Carefully pack and mail either insured Parcel Post, or U.P.S., attach a letter to outside of package explaining difficulty.